


DEFROSTER FAN KIT OPTION

Part No. 4-13140

MOUNTING INSTRUCTIONS

With Parts Listing and Drawing





BOX 70 • LITCHFIELD, MINNESOTA 55355-0070 (320) 693-3221 Fax: (320) 693-7252 www.800cabline.com

MOUNTING INSTRUCTIONS With Parts Listing

On John Deere X700 Series the fan must be mounted to the headliner panel. **DO NOT DRILL**INTO UPPER SIDE MEMBERS OR ROLL BAR TUBE. Doing so will compromise ROPS

protection and the ROPS certification.

- 1. Fasten the fan to the headliner with three #10-24 x .625 screws. Lower headliner and remove hole plugs in fan mount location. If not pre-drilled use the fan to mark (3) .25+ holes. Drill (1) .50+ hole in center of hole pattern for wires. See drawing for suggested location.
- A. Fasten the fork end terminal to the end of the black wire. See drawing.
- B. Fasten the butt splice terminal to the end of the red wire. See drawing.
- C. Strip both ends of the red wire provided and fasten one end of the wire to the butt splice terminal. Fasten the female slide terminal to the other end. See drawing.
- 2. Slide the fork end terminal under the nut of one of the mounting screws and tighten.
- 3. Route the red wire to the fuse block. Slide the female connector on to an open terminal on the fuse block. Insert the 10 amp fuse into the slot next to where you attached the female slide connector.

